Site name	Site code	Date of visit	os x	OS Y	Latitude	Longitude	UTM
							31U 293634.76E,
Greenwich 4	GR4	31/07/2007	543982	174676	51 27' 10N	0 04' 15E	5684119.83N

# Satellite pictures

Date: 12/05/2006 -10/09/2006

Local scale (100 m radius)






Meso Scale (1km radius)



Local scale (100 m radius)

Meso Scale (1km radius)



# Site classification

LAQN	
Classification	Station Type
	Urban
Suburban	Meteorological

### Urban climate zone

Meso (2 km radius)	Local (1km radius)	Micro (100 m radius)
4	6	6

### % Land cover

	100 m	1 km
Vegetated	83.4	68.5
Built over	9.81	20
Water	0.47	0
Road	6.33	11.6

# Main Land use

	Land use (MAJOR /
Direction	minor)
	RECREATIONAL
N	(golf)/ park
	RECREATIONAL/
E	residential
	GREEN SPACE/
S	residential
	RECREATIONAL/
W	residential

# Site description


Meso (2 km radius)	Local (1km radius)	Micro (100 m radius)
In general it was a vegetated	There was a fairly busy road behind the	
area with open space,	vegetated are on which the site was	A pond about 3m away, dense tree cover.
amongst which residential	placed. There was generally a lot of foliage	Site on top of a building with a car park
areas were scattered.	all around.	nearby.

## Station photo



Plan view diagram (30 m radius)

<u>KEY</u> □ : Tree X : Station




### Site obstacles

Sketch key	Type	Detail	material	Doof motorial	
		20101	matenai	Roof material	View from station
1	Shed	N/a	Wooden half covered in foliage	Wooden	Nation 1. It
2	Building	1st storey roof	Light brick	Corrugated metal	Surrouri
3	Building	2nd storey roof	N/a	Corrugated metal	2 3100/02/12/14
4	Building	Behind the site	Light brick	grey clay tiles	A STATE OF THE STA
£	troo	Evergreen	N/a	N/a	31/07/2007 12:15
	3	2 Building  3 Building  4 Building	2 Building 1st storey roof  2nd storey roof  3 Building roof  Behind the site	2 Building 1st storey roof Light brick  3 Building 2nd storey roof N/a  Behind the site Light brick	1 Shed N/a covered in foliage Wooden  1st storey roof Light brick Corrugated metal  2 Building 2nd storey roof N/a Corrugated metal  4 Building Behind the site Light brick grey clay tiles

	1			T	
6	Tree	Evergreen	N/a	N/a	- Tag
_					
7	Building	2 storey	Light Brick	flat metal roof	31.07.2007 12 18
8	Group of trees	Deciduous	N/a	N/a	
9	Group of trees	Deciduous	N/a	N/a	III and the Control of the Control o
10	Group of trees	Deciduous	N/a	N/a	
11	Tree	Deciduous	N/a	N/a	Unavailable
12	Tree	Deciduous	N/a	N/a	3100
13	Shed	N/A	wood	Dark asphalt	
10	Jilou	. 1// 1		Dan aophait	
14	Tree	Large Evergreen	N/a	N/a	Name of the state
15	Road	N/a	Asphalt	N/a	S averaged 13 to
		,	. 10   11   11		
16	Pond	Very small	water	N/a	Unavailable

Instrument diagram (Plan view)




#### Instruments

			True height		
Sketch key	Name	Variable	(m)	Concerns	
	Cup			Tall trees enclose the site undoubtedly	
а	anemometer	Wind Speed	9.47	affecting the wind speed.	
	Young wind	Wind		Tall trees enclose the site undoubtedly	
b	vane	Direction	9.47	affecting the wind speed.	
	TEO. 4	A. O. III		l	
С	TEOM	Air Quality	3.23	N/a	
				lug i i i i	
		Air		Windows on the second storey are	
d	N/a	temperature	N/a	very close to temperature sensor	

# Instrument image



**Graphs**Height vs.
bearing



# Other influences

### **Heat sources**

Bearing from site (°)	Source	Location	Detail
54 450	14.5		Windows on the second storey are
54 - 158	Windows	South-facing side	very close to temperature sensor

### Traffic

54 - 158	Windows	South-facing	g side very close to	temperature sensor	]
			12		
		Seasonal	Summer however there we	ere Temporary fixtures	
Alongside a	quiet road	features	evergreens present.		N/A

Task	Initial
Who visited	
the site	RW, KR
Who filed the	
report	KR, RE
Who produced the plots	KR

N.B. values given to 3 s.f.